

Installationsanleitung Montagerahmen IP67 309588

Installation guide mounting frame IP67 309588


Instructions de montage cadre de montage IP67 309588



A – Montage der Einzelteile / Assembly of the individual parts

A1

Attention!
Achtung!




030.6648

When assembling the panel mounting frame, the hole dimensions and spacing necessary for drilling and for cutouts as shown on the second page and fig. on top must be observed.


- These panel mounting frames can only be used with the inserts from the table on the second page.
- Check the **position of the sealing lip** with the panel mounting frame while mounting the flat gasket!
- **Tightening torque: screw M3 + nut 0,5 - 0,6 Nm**

Bei der Montage der Anbaurahmen sind die notwendigen Lochabmessungen und -abstände der erforderlichen Bohrungen und Montageausschnitte gemäss der Abbildung auf der Rückseite und der Abbildung oben einzuhalten.

- Diese Anbaurahmen können nur mit den Einsätzen aus der Tabelle der Rückseite verwendet werden.
- Bei der Montage der Flachdichtung ist auf die **Ausrichtung der Dichtlippe zum Anbaurahmen** zu achten!
- **Anzugsdrehmoment: M3 Schrauben mit Mutter 0,5 - 0,6 Nm**



B1



030.6649

Headquarters

Switzerland

Reichle & De-Massari AG
Binzstrasse 32, CHE-8620 Wetzikon

Tel HQ +41 (0)44 933 81 11

Fax HQ +41 (0)44 930 49 41

E-Mail hq@rdm.com

www.rdm.com



865404/A/08.2019

Please note:

This guide shows the best practices for installation **ONLY**. R&M expressly disclaims all liability for any damage to material, equipment, and for any injury or death. Legal health and safety regulations should have priority over best practices as shown in this guide. R&M does not guarantee this guide to be free of errors. Products included may vary from products shown. Please exercise caution.