

Installationsanleitung FO Field LC Pigtail


Installation guide FO Field LC Pigtail

Instructions de montage FO Field LC Pigtail




A - Preparation / Vorbereitung


A1 FO Field LC




A2 Kontrolle / Control



A3 Prüfmittel / Testing equipment




A4




B - Assemblierung / Assembling


B1




B2 Fiber Vorbereitung / fiber preparation



B3 Faser zurück stossen / *Push fiber back*




B4 Optional




B5 Cleaven / *Cleave*




B6









B7








B8





C - Demontage / Disassembly



Headquarters

Switzerland

Reichle & De-Massari AG

Binzstrasse 32

CHE-8620 Wetzikon

Telephone HQ +41 (0)44 933 81 11

Telefax HQ +41 (0)44 930 49 41

E-Mail hq@rdm.com

www.rdm.com

R&M

Please note:

This guide shows the best practices for installation **ONLY**. R&M expressly disclaims all liability for any damage to material, equipment, and for any injury or death. Legal health and safety regulations should have priority over best practices as shown in this guide. R&M does not guarantee this guide to be free of errors. Products included may vary from products shown. Please exercise caution.