

Installationsanleitung FO Field SC Pigtail


Installation guide FO Field SC Pigtail

Instructions de montage FO Field SC Pigtail




A - Preparation / Vorbereitung


A1 FO Field SC




A2 Kontrolle / Control



A3 Prüfmittel / Testing equipment




A4










B - Assemblierung / Assembling






B1





B2 Fiber Vorbereitung / fiber preparation







C - Demontage / Disassembly



Headquarters

Switzerland

Reichle & De-Massari AG
Binzstrasse 32
CHE-8620 Wetzikon
Telephone HQ +41 (0)44 933 81 11
Telefax HQ +41 (0)44 930 49 41
E-Mail hq@rdm.com

www.rdm.com

R&M

Please note:

This guide shows the best practices for installation **ONLY**. R&M expressly disclaims all liability for any damage to material, equipment, and for any injury or death. Legal health and safety regulations should have priority over best practices as shown in this guide. R&M does not guarantee this guide to be free of errors. Products included may vary from products shown. Please exercise caution.